

Ship Name: **CHEM FORTUNE**
IMO Number: **8318752**
Date Detained: **9/17/99**
Port: **St. Croix, USVI**

Ship Type: **Tankship (Not Specified)**
Flag: **Panama**
Class Society: **Det Norske Veritas**
Company(s): Owners, Operators or Managers
Mofel Shipping Corporation
Magnus Carriers Corporation

Deficiencies: Code - Category
0630 - Launch arrangt. for survival craft
1440 - Bilge pumping
1730 - Oily-water separating equipment
0720 - Fire fighting equipment

Description
Port lifeboat davit winch brake and associated equipment improperly maintained and
Cargo pump room bilge pump inoperable.
Vessel's oily-water separator was inoperable.
Fire stations 3, 4, and 6 missing hoses, nozzles and spanner wrenches.

~~~~~  
Ship Name: **COOL LADY**  
IMO Number: **8317423**  
Date Detained: **9/29/99**  
Port: **San Diego, California**

Ship Type: **Refrigerated Cargo Carrier**  
Flag: **Cyprus**  
Class Society: **Nippon Kaiji Kyokai**  
Company(s): Owners, Operators or Managers  
**Dancer Marine Ltd.**

Deficiencies: Code - Category  
**0610 - Lifeboats**  
**1420 - Cleanliness of engine room**

Description  
**Starboard lifeboat motor inoperable.**  
**Excessive amount of oil leaking from starboard ship service generator; excessive, hazardous levels of oil in the engine room**

~~~~~  
Ship Name: **EXPLORER II**
IMO Number: **8025161**
Date Detained: **9/29/99**
Port: **Portland, Oregon**

Ship Type: **Bulk Carrier**
Flag: **Malta**
Class Society: **Lloyd's Register of Shipping**
Company(s): Owners, Operators or Managers
Explorer Ocean Navigation Ltd
Kristen Marine S. A.

Deficiencies: Code - Category
0725 - Fixed fire extinguishing installation

Description
Inoperative fixed extinguishing (CO2) system.

Ship Name: **FINIKAS** Ship Type: **Bulk Carrier**
IMO Number: **7634020** Flag: **Panama**
Date Detained: **9/29/99** Class Society: **Hellenic Register of Shipping**
Port: **Searsport, Maine** Company(s): Owners, Operators or Managers
Compania Maritima Foinikas

<u>Code - Category</u>	<u>Description</u>
1499 - Other (Prop. & Aux. Machinery)	Main engine cooling water piping severely deteriorated and leaking around coolers.
1270 - Doors	Main deck watertight doors from accommodation area to cargo deck
0740 - Pumps	Emergency fire pump exhaust leaking into compartment.
0936 - Steering gear	Port steering gear pump inoperable
0950 - Electric equipment in	Numerous, hazardous electrical deficiencies throughout the vessel: Unrepaired ground on 220 volt system; open electrical wiring throughout accommodation spaces; and wiring to steering gear directional valves was dangerously loose and improperly installed.

~~~~~

Ship Name: **FLAMINGO EXPRESS** Ship Type: **General Dry Cargo Ship**  
IMO Number: **7204215** Flag: **Belize**  
Date Detained: **9/8/99** Class Society: **International Register of Shipping**  
Port: **Miami, Florida** Company(s): Owners, Operators or Managers  
**DVW & Company, Inc.**

| <u>Code - Category</u>                        | <u>Description</u>                                                                                   |
|-----------------------------------------------|------------------------------------------------------------------------------------------------------|
| <b>1730 - Oily-water separating equipment</b> | <b>Oily-water separator was inoperable.</b>                                                          |
| <b>1721 - Retention of oil on board</b>       | <b>Separated oil discharge from OWS was plumbed into water ballast tank, instead of sludge tank.</b> |
| <b>1710 - Oil record book</b>                 | <b>Oily bilge water transfers from machinery spaces not logged in the Oil Record Book.</b>           |

~~~~~

Ship Name: **KILA** Ship Type: **General Dry Cargo Ship**
IMO Number: **7116406** Flag: **Panama**
Date Detained: **9/20/99** Class Society: **American Bureau of Shipping**
Port: **New Orleans, Louisiana** Company(s): Owners, Operators or Managers
Trinity Shipping Corp.

<u>Code - Category</u>	<u>Description</u>
1499 - Other (Prop. & Aux. Machinery)	Overboard discharge piping check valve wasted and leaking in way of steering gear
2020 - Fire drills	Crew unable to perform a satisfactory fire

Ship Name:	LEADER	Ship Type:	Bulk Carrier
IMO Number:	8105741	Flag:	Panama
Date Detained:	9/20/99	Class Society:	Lloyd's Register of Shipping
Port:	Baltimore, Maryland	Company(s):	<u>Owners, Operators or Managers</u> Leader Vessel Limited Partnership

Deficiencies:	<u>Code - Category</u> 0630 - Launch arrangt. for survival craft 2545 - Reports/analysis of non-conformities, etc.	<u>Description</u> Lifeboat davit brakes and release mechanisms inoperable. Master unfamiliar with SMS responsibilities; SMS documentation written in language not understood by the crew;
---------------	--	--

Ship Name:	MARITIME LAPIS	Ship Type:	Bulk Carrier
IMO Number:	8921420	Flag:	Hong Kong
Date Detained:	9/29/99	Class Society:	Nippon Kaiji Kyokai
Port:	Tampa, Florida	Company(s):	<u>Owners, Operators or Managers</u> IMC Shipping Co. Pte Ltd Lapis Navigation Co.

Deficiencies:	<u>Code - Category</u> 2025 - Abandon ship drills	<u>Description</u> Vessel's crew unable to perform satisfactory abandon ship drill.
---------------	---	---

Ship Name:	MENDIONDO	Ship Type:	General Dry Cargo Ship
IMO Number:	7713204	Flag:	Portugal
Date Detained:	9/19/99	Class Society:	Bureau Veritas
Port:	Houston, Texas	Company(s):	<u>Owners, Operators or Managers</u> Caribbean Seatrade Corp.

Deficiencies:	<u>Code - Category</u> 0936 - Steering gear 0699 - Other (Life Saving Appliances)	<u>Description</u> Vessel is not equipped with an auxilliary steering system. Many serious lifesaving equipment deficiencies: Ring buoy lights inoperable; lifeboats missing survival equipment; lifeboats missing operating instructions; lifeboats missing retro-reflective tape.
---------------	---	---

Ship Name: **NORMAN**
IMO Number: **6817601**
Date Detained: **9/1/99**
Port: **Agat, Guam**

Ship Type: **Cement Carrier**
Flag: **Panama**
Class Society: **Nippon Kaiji Kyokai**
Company(s): Owners, Operators or Managers
Asian Carriers, Inc.

Deficiencies: Code - Category
1730 - Oily-water separating equipment
0230 - Number/composition (manning)
0988 - Deck - corrosion

1270 - Doors

1420 - Cleanliness of engine room

Description
Oily-water separator inoperative.

Vessel not manned in accordance with safe manning certificate.

Vessel is structurally deficient: Main deck wasted and holed in several locations; #3 fuel oil tanktop improperly repaired with temporary, concrete patch.

Door to superstructure improperly maintained, and no longer watertight.

Excessive amount of fuel oil in the engine room bilge.

~~~~~  
Ship Name: **PANAMAX STRENGTH**  
IMO Number: **8204420**  
Date Detained: **9/27/99**  
Port: **New Orleans, Louisiana**

Ship Type: **Bulk Carrier**  
Flag: **Cyprus**  
Class Society: **American Bureau of Shipping**  
Company(s): Owners, Operators or Managers  
**Cyprus Maritime Co Ltd.**  
**Nafpaktos Shipping Co. Ltd**

Deficiencies: Code - Category  
**0740 - Pumps**

Description  
**Emergency fire pump inoperable.**

~~~~~  
Ship Name: **PEARL OF ABU DHABI**
IMO Number: **8518106**
Date Detained: **9/26/99**
Port: **Seattle, Washington**

Ship Type: **Bulk Carrier**
Flag: **Cyprus**
Class Society: **Bureau Veritas**
Company(s): Owners, Operators or Managers
Drybulk Maritime Ltd,
Emirates Trading Agency

Deficiencies: Code - Category
0740 - Pumps

Description
Emergency fire pump inoperable.

Ship Name: **PYTHAGORAS**
IMO Number: **7708728**
Date Detained: **9/16/99**
Port: **Tampa, Florida**

Ship Type: **Bulk Carrier**
Flag: **Cyprus**
Class Society: **American Bureau of Shipping**
Company(s): Owners, Operators or Managers
Plaka Shipping Corp.
Navina Maritime, S.A.

Deficiencies: Code - Category
2020 - Fire drills

2025 - Abandon ship drills

Description
Crew unable to demonstrate satisfactory fire drill.

Crew unable to demonstrate a satisfactory abandon ship drill.

~~~~~  
Ship Name: **STAR**  
IMO Number: **7618349**  
Date Detained: **9/15/99**  
Port: **San Juan, Puerto Rico**

Ship Type: **General Dry Cargo Ship**  
Flag: **Romania**  
Class Society: **Registrul Naval Roman**  
Company(s): Owners, Operators or Managers  
**Compania De Navigatie Maritima**

Deficiencies: Code - Category  
**0740 - Pumps**  
**2020 - Fire drills**  
**0610 - Lifeboats**

Description  
**The emergency fire pump was inoperable.**  
**Unsatisfactory fire drill.**  
**The starboard lifeboat falls and releasing gear were not properly maintained, nor ready for immediate use.**

~~~~~  
Ship Name: **STATE OF TRIPURA**
IMO Number: **7627376**
Date Detained: **9/27/99**
Port: **Philadelphia, Pennsylvania**

Ship Type: **General Dry Cargo Ship**
Flag: **Libya**
Class Society: **Indian Register of Shipping**
Company(s): Owners, Operators or Managers
Shipping Corporation of India

Deficiencies: Code - Category
0725 - Fixed fire extinguishing installation

Description
On-deck fire main piping was wasted, holed, and repaired with unsatisfactory temporary patches; water pressure unsatisfactory.